

Version 5.0.1 Software Release Notes

Product: Cyclops
Date: July 10, 2018
Release Number: 5.0.1
Files: Cyclops-v5-0-1.etc

Bug

• [PAS-73] - Cyclops Self-Test Span Is Lower Than In Older Versions



Version 5.0.0 Software Release Notes

Product: Cyclops
Date: April 25, 2017
Release Number: 5.0.0
Files: Cyclops-v5-0-0.etc

Bug

• [PAS-64] - Arithmetic overflow can happen when checking a railed signal against threshold

Improvement

• [PAS-67] - Adjust ADC configuration to deal with magnetized lubricators

Task

• [PAS-68] - Remove Sample History handling code and reserved flash blocks



Version 4.0.1 Software Release Notes

Product: Cyclops
Date: March 25, 2015
Release Number: 4.0.1
Files: Cyclops-v4-0-1.etc

Bug

• [PAS-59] - 1 Hr regular strap causes arrival trip in some cases

Notes

Systems affected:

- Systems where the Cyclops sensor is continuously powered
- Systems that turn on the Cyclops sensor at the start of every rise cycle and the rise cycle is greater than 1 hour.

These systems may see false detections of plunger arrivals on version 4.0.0. Higher sensitivity settings (5-7) and systems where the baseline signal is large are more likely to be affected.



Version 4.0.0 Software Release Notes

Product: Cyclops

Date: December 17, 2014 **Release Number:** 4.0.0 **Files:** Cyclops-v4-0-0.etc

Critical Notes

None

Bug

- [PAS-37] On startup the SET pin is toggled which causes excessive current draw
- [PAS-43] Cyclops missing arrivals
- [PAS-57] Self-test pin I/O state not initialized
- [PAS-58] Change mag sensor reset pulse width to 10 microseconds

New Feature

- [PAS-34] Add Bootstrap feature for Cyclops Rev 2
- [PAS-35] Change default ADC Configuration regarding VREF
- [PAS-36] Implement self-test for new hardware
- [PAS-38] Increase sample rate during self-test
- [PAS-55] Allow magsensor HW reset to be disabled via INFO memory option
- [PAS-56] Support for HW version 4



Version 3.1.0 Software Release Notes

Product: Cyclops
Date: April 14, 2014
Release Number: 3.1.0
Files: Cyclops-v3-1-0.etc
Scope: New Feature Release

Critical Notes

None

New Features

• [PAS-24] - Implement manufacturing test for dial switch

Bug Fixes

• None

Outstanding Issues

None

Outstanding Features

None